

United States Of America
Department of Transportation - Federal Aviation Administration

Supplemental Type Certificate

Number SA00570WI

This Certificate issued to: Compro Aviation, Inc.
Renner Field, P.O. Box 508
Goodland, KS 67735

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 21.25(b) of the Federal Aviation Regulations.

Original Product - Type Certificate Number: A19SW

Make: Air Tractor, Inc.

Model: AT-602, AT-802, AT-802A

Description of Type Design Change: Installation of a Compro Aviation, Inc. Driftfinder DFS-10 system which injects oil into the engine exhaust to produce smoke in order to determine wind speed and direction. Data Required: (1) A copy of this certificate; (2) Compro Aviation, Inc. "Master Drawing List Air Tractor, Inc. Model#'s, AT-301, AT-400, AT-400A, AT-401, AT-401A, AT-401B, AT-402, AT-402A, AT-501, AT-502, AT-502A, AT-502B, AT-503, AT-503A, AT-602, AT-602A, AT-802, and AT802A." dated June 23, 1997 or later FAA approved revision.

Limitations and Conditions: Compatibility of this design change with previously approved modifications must be determined by the installer. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: May 30, 1995

Date reissued:

Date of issuance: September 4, 1997

Date amended:



(Title)

By direction of the Administrator

James M. Peterson
(Signature)

James M. Peterson
Associate ACO Mgr., Systems & Propulsion
Wichita Aircraft Certification Office

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.